


- Easy Assembly
- No Special Tools
- Reusable
- Saves Time and Cost
- Hy-Lok Tube Adapter

Tube Adapter





Part Number	Hose Size	Tube O.D.	L Overall Length	L, Cut-off Length
H-POTA 4 - 4	4	1/4"	1.91"	1.15"
H-POTA 6 - 6	6	3/8"	2.02"	1.15"
H-POTA 8 - 8	8	1/2"	2.42"	1.37"
H-POTA 4 - 6M	4	6mm	48.5mm	29.2mm
H-POTA 6 -10M	6	10mm	51.3mm	29.2mm
H-POTA 8 -12M	8	12mm	61.5mm	34.8mm


ASSEMBLY

- 1. Lubricate fitting with light oil.
- 2. Push hose onto fitting until hose bottoms into plastic cap.



Male Adapter





Part Number NPT (ISO R7/1)	Hose Size	P NPT/ISO Pipe Threads	H Hex Flat	L Overall Length	L, Cut-off Length
H-POMA 4 - 4N(R)	4	1/4"	9/16"	1.68"	0.92"
H-POMA 6 - 4N(R)	6	1/4"	11/16"	1.80"	0.93"
H-POMA 6 - 6N(R)	6	3/8"	11/16"	1.80"	0.93"
H-POMA 8 - 8N(R)	8	1/2"	7/8"	2.19"	1.15"



DISASSEMBLY


- Slice hose lengthwise from plastic cap to fitting end.
- Flex hose to expose hose ends. Remove by quickly pulling hose.





Straig Union





Part Number	Hose Size	L Overall Length	L. Cut-off Length	
H - POU - 4	4	2.07"	0.55"	
H-POU-6	6	2.25"	0.52"	
H-POU-8	8	2.61"	0.52"	

■ HOW TO ORDER

Use \$316 for 316 Slainless Steel or BRAS for Brass as a prefix to the Part Number.



HY-LOK CORPORATION